Appendix A

MINE PHOTOGRAPHS



Photo 1: Two-Tiered Waste-Rock Dump at the Firefly/Pygmy Mine.



Photo 2: Lower Dump at the Firefly/Pygmy Mine.



Photo 3: Mine Adit at the Firefly/Pygmy Mine




Photo 4: Abandoned Cabin at the Firefly/Pygmy Mine




Photo 5: Mine Adit at the Vanadium Queen Mine



Photo 6: Office/Shop Structure and Transformer Station at Vanadium Queen Mine



Photo 7: Cribbed Upper Slope of Mine Dump at Vanadium Queen Mine



Photo 8: Lower Slope of Mine Dump at Vanadium Queen Mine



Photo 9: Waste-Rock Dump at the Blue Cap Mine



Photo 10: Mine Bench at the Blue Cap Mine




Photo 11: Primary and Secondary Adits at Blue Cap Mine




Photo 12: Primary Adit at the Blue Cap Mine



Photo 13: Toe of Blue Cap Mine Dump along Lion Canyon Creek



Photo 14: Blue Cap Mine Dump




Photo 15: Black Hat Mine



Photo 16: Portal House at the Black Hat Mine



Photo 17: Ore Loadout Structure at the Black Hat Mine



Photo 18: Saint Patrick Mine Dump